

Affected Product: ColdMak

Effective Date: 11-May-2022

Device Identification: ColdMark -3C/26F

ColdMark 0C/32F ColdMark 2C/36F ColdMark 5C/41F ColdMark 10C/50F

Description & Purpose:

- * Supply chain shortages have required SpotSee to consider different alternatives for the backing of the ColdMark.
- * The paperboard used on the back of the ColdMark units is unavailable at the present time.
- * While we continue to explore alternatives, we have put in place a method to seal and mount the indicators with a brown adhesive backing.
- *This change does not affect the intended use or performace of the product.
- *The change is temporary and will be in place only until SpotSee secures a paperboard solution.

Images of new solution are below:



This change will not affect product's form, fit, or function.

Sara Busteed

May 13, 20

Quality Representative

Date